

## ABSTRACT

A device and method to move a fuel assembly of a nuclear reactor, wherein the device eliminates the potential for dropping the fuel assembly due to stress corrosion cracking of the upper guide thimble sleeves that attach the top nozzle to guide thimbles.